



2006 Citation CJ1+ | S/N 525-0620 | N5UD



MAX CRUISE SPEED
389 Ktas



PASSENGERS
5



RANGE(NM)
1,300 nm



SPECIFICATIONS

2006 Citation CJ1+ | S/N 525-0620 | N5UD

AIRFRAME

Hours Since New: 799

Cycles Since New: 527

ENGINES

William International | FJ44-1AP (FADEC) **TAP Blue**

Serial Number (L) 180047 | (R) 180044

Total Hours Since New 799 | 799

Cycles Since New 527 | 527

Time Between Overhauls 5,000 | 5,000

INSPECTIONS

Williams TAP BLUE \$240 150hr & Pro-Parts \$137 150HR

Maintained by Cessna (San Antonio)

DOC-10 36m/1,200hr c/w Aug. 2017

CESCOM Maintenance Tracking

ADS-B Compliant S/B (525-34-90)

RVSM Certified

AVIONICS

EFIS: Collin Pro Line 21 3-tube 8x10-inch

F/DIR : Collin FGC-3000 IFCS

A&P: Collin FGC-3000 IFCS

Weather Radar: Collins WXR-800

COMMS: Dual Collins VHF-4000 w/8.33 spacing

NAVS: Dual Collins NAV-4000 & NAV-4500 w/FM immunity

Radar Altimeter: ALT-4000

FMS: Collins FMS-3000 (4.0 WAAS) w/GPS- 4000S

GPS: Garmin GPS-500

DME: Collins DME-4000

Compass: Dual Collins AHC-3000 AHRS

TRANS: Dual Collins TDR-94 Mode S (ADS-B 34-90)

Hi Frequency: Collins HF-9000 provisions

TAWS: Honeywell Mark VII EGPWS

TCAS: BFGoodrich Skywatch HP TCAS-I

These specifications are informational only and subject to verification upon inspection. They do not constitute representations or warranties of any kind. The aircraft is subject to prior sale, and/or removal from the market.





SPECIFICATIONS

2006 Citation CJ1+ | S/N 525-0620 | N5UD

ADDITIONAL EQUIPMENT

Collins IFIS 6.0 Upgrade

IFIS-5000 Charts w/ FSU-5010 File Server

Collins XM Weather Satelite

Collins RTU-4210 radio tuning unit

Artex C406-2 ELT w/nav interface

Dual Collins ADC-3000 air data computers

L3 GH-3000 ESIS

EROS crew oxygen masks

50 cubic foot oxygen system

Pulselites, tail flood

Lead Acid Battery

EXTERIOR

Snow white w/platinum, deep red & blue stripes

INTERIOR

Configuration: Executive 6 Pax

Seating: Townsend Tan leather seating, forward RS side-facing seat & 4-place mid-cabin club, Aft LS belted lav seat, Forward LS refreshment center, dual executive writing tables and wood work in gloss bronze ribbon mahogany laminate cabinetry, textured print headliner with coordinating tan side wall and sandstone carpet.

LOCATION: San Marcos, TX (KHYI)

These specifications are informational only and subject to verification upon inspection. They do not constitute representations or warranties of any kind. The aircraft is subject to prior sale, and/or removal from the market.





BLACK SERVICE[®]

ABOUT US

Valor Jets is an international aircraft sales, marketing, acquisitions and consulting firm with coast-to-coast office locations. We cater to the elite business jet owners, flight departments and financial institutions. Our experts carefully blend each area of expertise into a truly integrated approach.

HEADQUARTERS
3983 DESTINATION DRIVE
UNIT 207
OSPREY, FL 34229
P: 941.201.1211

LOS ANGELES
7000 MERRILL AVE.
CHINO, CA 91710
P: 909.342.6203

TAMPA
TAMPA INTERNATIONAL AIRPORT
2450 N. WESTSHORE BLVD.
TAMPA, FL 33607
P: 813.452.6277

